JB Combustion Itd

Non Domestic Gas Safety Record

Cert. No. 1132

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure No detailed internal inspection of flues (integrity, construction and lining) has been carried out.

Company / Installer						Job Address								Cu	Customer / LandLord											
Engineer		Karan Patel				Name								Na	me											
Company Address Post Code		JB Combustion ltd				Address	Study Inn Triumph House							Co	mpany		Study Inn									
							3	Triumph	Road						Address											
		Althorne Road					N	ottinghan	า																	
		Redhill Surrey RH1 6EF				Post Code Tel. No		_																		
							e N	G7 2GA						Post	ost Code											
														Tel. No												
Tel No.																										
Gas Safe Reg		07799174328 549817																								
טו	Card No.																									
Ар	pliance De	etails							Inspection	Details																
	Location		Appliance Type	Make	Mode	el	Flue Type	Landlord's Appliance	Appliance Inspected		Heat Input	(kW/h) H					Safety device(s		Visual condition	Flue	Appliance	Appliance safe				
												R	Reading Ratio CO				correct operation	Provision satisfactory	of flue and termination	Performance test	Serviced	to use				
													ppn	n %		opm %			satisfactory							
1	Plantroo	m Wa	ater Heater 1	AO SMITH	CYCLONE 3	BFC100	OF	Yes	Yes	20	100.		0000 2	\rightarrow		\rightarrow		Yes	Yes	Pass	Yes	Yes				
2	Plantroo	m Wa	ater Heater 2	AO SMITH	CYCLONE 3		OF	Yes	Yes	20	100.			_	_	_		Yes	Yes	Pass	Yes	Yes				
3 Plantro		m Wa	ater Heater 3	AO SMITH	CYCLONE 3	BFC100	OF	Yes	Yes	20	100.	7 0.0	0.0000 0		0.0000	0 8.9	Yes	Yes	Yes	Pass	Yes	Yes				
4																										
5																										
6																										
De	fects / Ide	entified										Emerc	gency C	ontrol	Access	ible Ye	es Gas T	iahtness S	atisfactory \	'es						
	Labels and Warning										e Issued	elssued														
1		Hot surface ignitor and Flame sensor has signs of age. Service Kit fails.					rface igii	ntor inclu	ded required be	efore it	NA	Gas In	nstallatio	on Pipe	ework Visual Inspection Satisfactory Yes											
									Equipotenti																	
	2	Hot surfac	ce ignitor and Fla	ame sensor has signs of ag	with Hot Su	t Surface igintor included required before it				NA																
Н	3	fails.									NA	NEXT INSPECTION DUE ON OR 06-Sep-2026														
4 5		Hot surface ignitor and Flame sensor has signs of age. Service Kit with Hot Surface igintor included required befails.									NA BEFORE				KE											
												-														
	6																									
Comments																										
Local tightness test passed																										

Print Name

Issued by:

Signed

Karan Patel

Received Signed

Print Name

by:

Date

07-Aug-2025