säfe JB Combustion Itd

Non Domestic Gas Safety Record

Cert. No. 1131

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure No detailed internal inspection of flues (integrity, construction and lining) has been carried out.

Company / Installer					Job Address							Custo	Customer / LandLord								
Eng	Engineer Karan Patel			Name						Name											
Company Address		JB Combustion ltd 30 Althorne Road Redhill				Address	S	Study Inn Walnut Gardens Exeter					Compa	ny	Ladrillos						
							٧						Addres	S	Unit 15 Hackett Way Fareham						
							E														
		Surrey				Post Code	e E	EX44DH							Hampshire						
Post Code Tel No. Gas Safe Reg		RH1 6EF 07799174328				Tel. No							Post Co	Post Code	PO141TH						
													Tel. No		LOTATIII						
													Tel. No	Tel. NO							
ID Card No.		3 34301/																			
ישו	Caru No.																				
Арі	pliance D	etails							Inspection	Details											
	Location	n	Appliance Type	Make	Mod	lel	Flue Type	e Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	/h) High Combo		Combustion Reading	Safety device(s) correct	Ventilation Provision	Visual condition of flue and	Flue Performance	Appliance Serviced	Appliance safe to use	
												Ratio CC	CO2 % Ratio CO C		operation	satisfactory	termination satisfactory	test	Scricca	to use	
	Diametera		U Dalland	A d	Ffl- F-0	C (200 l-	D.C.		V	20	102.6	ppr		ppm %		V	-	D		V	
1	Plantro		Hws Boiler 1	Andrews	Ecoflo Ec9		RS	Yes	Yes	20	102.6	0.0000 3	-	-		Yes	Yes	Pass	Yes	Yes	
2	Plantro	om	Hws Boiler 2	Andrews	Ecofo Ec	66/380	RS	Yes	Yes	20	102.6	0.0001 7	8.7 NA	NA NA	Yes	Yes	Yes	Pass	Yes	Yes	
3																					
4																					
5																					
6																					
Def	fects / Id	entified							Labole and	Warning Notice	o lecued	Emergency Co	ontrol Acc	essible Y	es Gas T	ightness S	atisfactory \	′es			
	Labels and W									_		Cas Installation Bingwork Visual Inspection Satisfactory Vac									
	Expansion Vessel looks like it is cracked. Only a matter of time untill it pops. Hot water Cylinder has corrosion at base of the tank internally. Signs of leakage at base of tank externally. Heater is on it last legs. Replace before it									NA	Gas Installation Pipework Visual Inspection Satisfactory Yes										
Н	2 Expansion Vessel looks like it is cracked. Only a matter of time untill it pops. Hot water Cylinder has corrosion at										NA	Equipotential Bonding Yes									
	-		ne tank internally.			NEXT INSPECTION DUE ON OR 13-Aug-2026															
	3					BEFORE	CTION DUE ON OR 13-Aug-2026														
4																					
5																					
	6																				
Coi	mments																				
Г	Less Cos T	Ciabbassa ta	at was a sal																		
	Local Gas 1	Fightness te	st passed																		
	natures																				
Issued by:							eceived Signed							Date 06-Aug-2025							
			Karein Pa	le(ŀ	by:															
				,																	
Pri	nt Name		Karan Patel			Print Name															