this

Contractor's Reference Number

been defaced or altered

if the serial number has DPN// UUJJJUU

CRN/ Issued in accordance with British Standard 7671 - Requirements for Electrical Installations by an Approved Contractor or Conforming Body enrolled with NICEIC, Warwick House, Houghton Hall Park, Houghton Regis, Dunstable LU5 5ZX. TYPE OF INSTALLATION Domestic dwelling | Transportable unit | Domestic dwelling | Transportable unit | Transportable unit | Domestic dwelling | **DETAILS OF THE CLIENT** 

MR. David Pierre Address: 2 Wann Mir FFail IsaF. RCT CF3BIAX Postcode:

**PURPOSE OF THE REPORT** report is required:

Date(s) on which inspection and testing were carried out: 08.01.16

DETAILS OF THE INSTALLATION

Occupier: Unhnown

Date of previous inspection:

39 Malvern berrace, Brynmill

Suansea. Estimated age of the electrical installation: 20 years

Evidence of alterations or additions

Electrical Installation Certificate No or previous Periodic Inspection or Condition Report No:

Records of installation Records held by: available.

This report should have been reviewed and confirmed by the registered Qualified Supervisor of the Approved Contractor responsible for issuing it. (See declaration on page 2) This report is based on the model forms shown in Appendix 6 of BS 7671.

Published by Certsure LLP. Certsure LLP operates the ELECSA & NICEIC brands. © Copyright Certsure LLP (July 2015)

**EXTENT OF THE INSTALLATION AND LIMITATIONS ON THE** INSPECTION AND TESTING

Extent of the electrical installation covered by this report:

All Fixed Installation of All Bedrooms Bothward

sono lan-mas spiritual exculted Agreed limitations including the reasons, if any, on the inspection and testing

5.2 7.7.

of the installation:

Operational limitations including the reasons (see page No.

RCD 1 Orcuit 2 lights Rear Ubble to loop lest or Continuity lest

The inspection and testing have been carried out in accordance with BS 7671, as amended. Cables concealed within trunking and conduits, or cables and conduits concealed under floors, in inaccessible roof spaces and generally within the fabric of the building or underground, have not been visually inspected unless specifically agreed between the client and inspector prior to the inspection.

SUMMARY OF THE CONDITION OF THE INSTALLATION

General condition of the installation (in terms of electrical safety)

Adaquate at Prescent.

Summary of the condition of the installation continued on additional pages? No

Yes Specify page No(s):

Overall assessment SATISFACTORY / OMSAMSFACTORY Delete as appropriate

\* An 'Unsatisfactory' assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified, or that Further investigation without delay (FI) is required

Page 1 of