

Annual Electrical Safety Record - E2



The Old Bakery
14b The Green
West Drayton
Middlesex
UB7 7PJ
TEL : 0800 587 9999



Date : Monday, 18 January, 2016

Client : Make ur Move
213-215 Ducie House Ducie Street
Manchester
M1 2JW

Cert. No : CT-505417-1006053001

Site Add. : 141 Newnham Avenue
Bedford
Beds
MK41 9QA

INSTALLATION INSPECTION (Visual & Functional)

Electrical supply details

Type : TN-S PIR/EICR Label present Yes Expires on 14/09/2005

Meter Reading 12,770
Meter Visual Inspection Pass

Main Earthing Conductor

Main Protective Bonding Conductors

Present Water : Yes Gas : Yes Other :

General Condition of Consumer Unit:- Good

RCD Test:- Yes Zs 0.97 Ω

Circuit Number	Description	Functional Check	Protective Device	Recommendations
1	Cooker point	Yes	BS (EN) 60898	
2	Socket outlets Throughout	Yes	BS (EN) 60898	
3	socket outlets lounge	Yes	BS (EN) 60898	
4	kitchen heater	No	BS (EN) 60898	
5	Lighting throughout	Yes	BS (EN) 60898	

APPLIANCE DETAILS/ ELECTRICAL EQUIPMENT RESULTS

ID	Location	Type	Make	Model	Serial No	Plug	Flex	Body	Continuity (ohms)	Insulation (megohms)	Functional Check	Comments	Passed Safety Test
1	Kitchen	Cooker Ignition	Indesit	I55GG	509073049	Pass	Pass	Pass	0.068	99.00	Pass	Class 1	Yes
2	Kitchen	Fridge/Freezer	Indesit	Not found	Not found	Pass	Pass	Pass	0.090	99.00	Pass	Class 1	Yes
3	Kitchen	Washing Machine	Beko	WM5102W	Not found	Pass	Pass	Pass	0.054	99.00	Pass	Class 1	Yes
4	Kitchen	Microwave	Kenwood	K25MSS11	Not found	Pass	Pass	Pass	0.060	99.00	Pass	Class 1	Yes
5	Kitchen	Kettle	Sainsbury	Basic	Not found	Pass	Pass	Pass	0.059	99.00	Pass	Class 1	Yes
6	Kitchen	Toaster	Sainsbury	Basic	Not found	Pass	Pass	Pass	0.048	99.00	Pass	Class 1	Yes
7	Kitchen	Iron	Sainsbury	Basic	Not found	Pass	Pass	Pass	0.084	99.00	Pass	Class 1	Yes

Details of any faults found and rectification work necessary

Warning Notice

1	No	This Safety Record Issued By
2	No	
3	No	
4	No	
5	No	
6	No	
7	No	

Next Inspection Due Within 12 Months

(Please refer to the documents titled "E2 comments" for comments made by the engineer for this inspection)

Name Michael Cooper

The report is a general, visual, surface and functional examination of the electrical system, which is accessible i.e. visible and readily available for inspection from ground and floor levels without risk of causing damage to the property or injury to the inspector and limited accordingly. Due care is therefore exercised throughout the inspection regarding safety, practicality and the constraints of being a visitor to the property (which may be occupied). So furniture, floor coverings and other contents are not moved, lifted and no part is forced or laid open to make it accessible. Loop impedance tests are only carried out on socket outlets. The report is provided solely for the use of the client and no liability to anyone else is accepted. Should the client not act upon specific advice contained in the report, no responsibility is accepted for the consequences. Gas-Elec Safety Systems, its employees or franchisees accept no liability for the consequences of any errors or omissions in this report.

THIS IS A VISUAL AND FUNCTIONAL INSPECTION ONLY

In the event of a complaint relating to any service or installation in a property **gas-elec** must be given the opportunity to address the issue by re-visiting the property to resolve any alleged complaint. **gas-elec** cannot be held responsible if the opportunity to fully address the matter is not afforded to us. In the event of another company/contractor being called to the property to investigate or attempt to rectify an alleged complaint in preference to **gas-elec** the company will accept no liability. Where passed safety test is VO, this is an abbreviation of visual only inspection.

E2 Comments



Brooklyn House,
Money Lane,
The Green,
West Drayton,
UB7 7PQ
TEL : 0800 587 9999



Date : Monday, 18 January, 2016

Client : Make ur Move
213-215 Ducie House Ducie Street
Manchester
M1 2JW

Cert. No : CT-505417-1006053001

Site Add. : 141 Newnham Avenue
Bedford
Beds
MK41 9QA

Observation

Meter not fixed to backing, hooked onto backing plate, recommend contacting supplier.

The notes on this page relate to the safety inspection carried out at the above property. Consideration should be given to having those items remedied or investigated further