



# British Gas

Looking after your world

## Contact us



[britishgas.co.uk/help](http://britishgas.co.uk/help)



**0800 107 7798\***

Mon - Fri 7am - 9pm. Sat - 8am - 6pm



British Gas, Swallowfield One,  
Wolverhampton Road, West  
Midlands B69 2BG

## Your HomeCare Number

**26218892 N090486**

## Your Landlord's Gas Safety Certificate is over the page

- n This is an important document.
- n You should take a few moments now to read it.
- n You may need to refer to this certificate in the future.
- n Please file it somewhere safe.

### Key to Appliance Type Abbreviations

AGA Aga	INS Installation Premise
BBC Back Boiler Circulator	LB Large Boiler
BBF Back Boiler Fire	LBX Extra Large Boiler
BCO CO Detector	MWH Multitpoint Water Heater
CGE Electric/Gas Cooker	OVN Gas Oven
CHB Central Heating Boiler	SLC Split Level Cooker
CIR Circulator	SA Smoke Alarm
CKR Gas Cooker	SWH Single Point Water Heater
DGF Decorative Gas Fire	WAC Warm Air Conditioner
FRE Gas Fire	WAL Wall Heater
FRB Back Boiler Fire	WAU Warm Air Unit
FRC Back Circulator Fire	WAW Warm Air Unit and Water Heater
GOB Gas Oven	WH Water Heater
GRL Grill	WS Sink Water Heater
HGE Electric/Gas Hob	
HOB Hob	

### Key to Engineer findings

NCS or NTCS	Not to current standards
AR	At Risk
ID	Immediately Dangerous
PRV	Pressure relief valve

## Additional Landlord information

If a "YES" has been entered in the column titled "Indicate YES if unable to test", then the Landlord/Agent must obtain additional evidence from any person undertaking subsequent work on the appliance, that the appliance is operating safely.



Gas Safe  
Registration  
Number

158205

# Landlord's Gas Safety Record

Landlords Inspection Service  
Swallowfield One  
Wolverhampton Road  
Oldbury  
West Midlands B69 2BG



This inspection is for gas safety purposes only in accordance with the Gas Safety (I & U) Regulations. Flues were inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the Flue integrity, construction and lining has not been carried out.

**TENANT DETAILS**

61 Havelock Street  
Loughborough  
LE11 5DH

**LANDLORD/AGENTS DETAILS**

Mr Panagiotios Mamuneas  
96 Fairstone Hill  
Leicester LE2 5RJ

APPLIANCE DETAILS						INSPECTION DETAILS								
	LOCATION	TYPE	MAKE	MODEL	FLUE TYPE	Operating Value (See Key below)	Safety Device Correct Operation	Ventilation Satisfactory	FLUE PERFORMANCE		Visual Condition of Flue and Termination Satisfactory	Appliance Safe	Requested To Test	Indicate* YES if unable to test
									Flue Flow Test	Spillage Test				
1	KITCH	HOB	BOSCH	HOB	FLUELESS	20m	Yes	Yes	N/A	N/A	N/A	Yes	Yes	---
2	KITCH	CHB	WORCS	G/STAR 24I	ROOM-SEALED	23.85k	Yes	Yes	N/A	N/A	Yes	Yes	Yes	---
3														
4														
5														
DETAILS OF ANY DEFECTS IDENTIFIED						REMEDIAL ACTION TAKEN			LABELLED AND WARNING NOTICE ISSUED YES/NO		GAS INSTALLATION TIGHTNESS TEST AND VISUAL INSPECTION OF GAS			
1	CLEARANCES					NONE			Yes		<div style="border: 2px solid black; padding: 10px; text-align: center;"> <b>NEXT SERVICE CHECK DUE WITHIN 12 MONTHS</b> </div>			
2	FLUE/PRV TERMINAL					NONE			Yes					
3														
4														
5														

This safety record is signed by electronic signature by

Print name GEORGE STEVENS 9509

Date 30 March 2016

Job No. 1366241977

Number of Appliances Tested ..2..... Page ....2..... of ....2.....

**IT IS A LEGAL REQUIREMENT THAT THIS RECORD BE KEPT FOR A MINIMUM PERIOD OF TWO YEARS**