## **Gas Safety Record**

Landlords Address

Montrose Residential Ltd

Scarletts House

Scarletts Lane, Kiln Green, Readng,

**Emergency Control Valve Accessible Yes** 

RG10 9XD

UK

Ahds Nh G.O.S. Heating Ltd

216 Strand Road, Ashton, Preston, Lancashire PR1 8UJ

Gas Tightness Satisfactory Yes

Phone: 01772 734966



175496

Earth Bonding Satisfactory Yes

Customer ID: 13526

Preston, Lancashire

GUILD TAVERN 20-22 Tithebarn St,

alan smith

PR1 1DJ

UK

	Date Rece	eived: 30/10/20	017 13:18:36 Compl	etion T	ime 23	3/11/20	17 10:54:29	P.O. No	P.O. Number:							tificate No: LC-13526/90128			
	Date Atter	ate Attended: 23/11/2017 10:20:38 Job Status: Completed							er: Kev	in Pickles	Registered ID: 4152691 Workorder ID: 90128						128		
		Appliance and Inspection Details																	
App ID	Room	Туре	Make/Model	Арр.	Flue	Inlet Pres.	or	Safety Device Correct Op.	Adequate	Flue Flow Test		,	Flue Visual Condition		Hi %	Hi Ratio	Yes/No/	Inspected Only	to use
				Owner	Туре	mBar	Heat Input	Yes/No/Na	Yes/No/Na	Pass/Fail/Na	Pass/Fail/Na	Yes/No/Na	Pass/Fail/Na	Lo ppm	Lo %	Lo Ratio	Installed	Yes/No	Yes/No
9157	boiler room	Boiler	Worcester greenstar	La	FF	n/a	40.0	Yes	Yes	n/a	Pass	Yes	Pass	86	9.7	0.0009	Yes	Yes	Yes
			40cdi conventional				kWh							15	9.4	0.0002			
Notes	LLGS service	eINV 29969 27/	11/17																

This inspection is for gas safety purpose only in accordance with the current Gas Safety (Installation and Use) Regulations. Chimney Systems/Flues were inspected visually and checked for satisfactory evacuation of products of combustion. A detailed inspection of the Flue integrity, construction and lining has not been carried out. This is not a guarantee of the reliability of the appliance.

Appliances recorded: 1 Serviced: 1 Inspected Only: 1

This safety record is issued by: Kevin Pickles

Gas Pipework Visual Inspection Satisfactory Yes

Date: 23/11/2017

Received By: Alan. Smith

NEXT SERVICE CHECK DUE WITHIN 12 MONTHS