



# Gas Safety Record

alan smith  
GUILD TAVERN 20-22 Tithebarn St,  
Preston, Lancashire  
PR1 1DJ  
UK

Landlords Address  
Montrose Residential Ltd  
Scarletts House  
Scarletts Lane, Kiln Green, Readng,  
RG10 9XD  
UK

Customer ID: 13526

G.O.S. Heating Ltd

216 Strand Road, Ashton, Preston, Lancashire  
PR1 8UJ

Phone: 01772 734966

Fax: 01772 720883



175496

Date Received: 29/10/2018 13:12:55    Completion Time 14/11/2018 10:24:49    P.O. Number:														<b>Certificate No: LC-13526/104419</b>					
Date Attended: 14/11/2018 10:11:14    Job Status: Completed    Engineer: Abdul Nasir UI-haq    Registered ID: 4312341    Workorder ID: 104419																			
Appliance and Inspection Details																			
App ID	Room	Type	Make/Model	App. Owner	Flue Type	Inlet Pres. mBar	Opr. Press. or Heat Input	Safety Device Correct Op. Yes/No/Na	Ventilation Adequate Yes/No/Na	Flue Flow Test Pass/Fail/Na	Flue Spillage Test Pass/Fail/Na	Termination Satisfactory Yes/No/Na	Flue Visual Condition Pass/Fail/Na	CO Hi ppm Lo ppm	CO2 Hi % Lo %	CO/CO2 Hi Ratio Lo Ratio	Serviced Yes/No/Installed	Inspected Only Yes/No	Safe to use Yes/No
9157	boiler room	Boiler	Worcester greenstar 40cdi conventional	La	FF	22	39.8	Yes	Yes	n/a	n/a	Yes	Pass	89	9.6	0.0009	Yes	Yes	Yes
							kWh							13	8.9	0.0001			
<b>Notes</b> landlords gas safety check, customer wnts jazz bar and guild tavern doing together (kl) [Engineers Comments] Serviced boiler and issued llgsc job complete - INV 34090 15/11/18																			
Gas Pipework Visual Inspection Satisfactory <input checked="" type="checkbox"/> Yes    Emergency Control Valve Accessible <input checked="" type="checkbox"/> Yes    Gas Tightness Satisfactory <input checked="" type="checkbox"/> Yes    Earth Bonding Satisfactory <input checked="" type="checkbox"/> Yes																			
This inspection is for gas safety purpose only in accordance with the current Gas Safety (Installation and Use) Regulations. Chimney Systems/Flues were inspected visually and checked for satisfactory evacuation of products of combustion. A detailed inspection of the Flue integrity, construction and lining has not been carried out. This is not a guarantee of the reliability of the appliance.																			

Appliances recorded: 1    Serviced: 1    Inspected Only: 1

This safety record is issued by: Abdul Nasir UI-haq

Date: 14/11/2018

Received By: Me. Me

**NEXT SERVICE DUE BY**  
**14/11/2019**