

## Domestic/Landlord Gas Safety Record Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. No detailed internal inspection of

flues (Integrity, Constructions and Lining) has been carried out.

Certificate Reference	
	_
	•

31 Vernon St

Certificate No:

Engineers Details Installation Details													Client D	Client Details						
Tra	ding Title	Reactfast Plumbing And Heating							allation	04 \/a==	Ctus	.1			Client Addres		Cloud Lettings 43a Carholme Rd			
Add	dress	62 Roman Wharf Lincoln							Address 31 Vernon Street Lincoln						, tadioo	Linc		a		
Post Code: LN1 1SR									Post Code:							Post Code: LN11RN				
	s Safe No:	544012 Telephone No: 07736941792					Tel	Telephone No:					Telephone No:							
A	Appliance Details Inspection Details																			
	Locatio	on Appliance Type		е Туре	Make		Model	CO2 Reading	CO Reading	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NA)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Kitchen	itchen Hob Lamona 4 Ring				-	-	FL	YES	Na	YES	18.5 mbar	YES	YES	N/A	N/A	NO	YES		
2	Kitchen	Combi boiler		er	Glowworm		GW 30CI	7.72	39	RS	YES	0.0007	YES	18 mbar	YES	YES	YES	N/A	NO	YES
3																				
4	4																			
5	5																			
Faults/Notes									Remedial Work Taken									Warning Notice Fixed		
1																				
2																				
3																				
4																				
5																				
	ergency Cont essible:	rol Valve	Y	Gas Tightr	ness Sat	isfactory: YES		Signatures Report Issued By:							Gas ID Number: 3493363					
Gas	s Installation F	Pipework	Visual Inspe	ection Sa	atisfactory		YES		_	harlie Morri							Wed-09-08-2017			
Number Of Appliances Tested: 2 Equipotential Bonding: YES Report Received By:																				
NEXT INSPECTION DUE ON OR BEFORE:  Thu-09-08-2018 Installation Pass: YES Name: Signed: Date:											Wed-0	Wed-09-08-2017								
CO /	Alarm fitted working?	NA	Smoke ala and worki		NA	This Gas	Safety Report was cre	ated by Ga	s Checker S	Software 20	116 all rights	s reserved	www.gasch	necker.co.uk						