

Synergy Heating Services Ltd
Stay safe with Synergy



Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

| Company / Installer | | Job Address | | Customer / Landlord | |
|---------------------|------------------------------|-------------|-------------------|---------------------|--------------|
| Engineer | Mark Kneath | Name | | Name | Mr Jez Fage |
| Company | Synergy Heating Services Ltd | Address | 146 | Company | |
| Address | 13 | | Rhyddings Terrace | Address | 43 |
| | Morgans Terrace | | Brynmill | | Swansea Road |
| | Briton Ferry | | Swansea | | |
| | Neath | Post Code | SA2 0DR | Post Code | Swansea |
| Post Code | SA11 2SY | Tel. No | | Tel. No | SA5 7JA |
| Tel No. | 07853260650 | | | | |
| Gas Safe Reg | 519419 | | | | |
| ID Card No. | 4618885 | | | | |

| Appliance Details | | | | | | Inspection Details | | | | | | | | | | | | | | | |
|-------------------|--------------------|----------------|--------|-----------------------|-----------|----------------------|---------------------|---------------------------|-------------------|-------------------------|--------|-------|------------------------|--------|-------|------------------------------------|------------------------------------|-------------------------------------------------------|-----------------------|--------------------|-----------------------|
| No | Location | Appliance Type | Make | Model | Flue Type | Landlord's Appliance | Appliance Inspected | Operating Pressure (mbar) | Heat Input (kW/h) | High Combustion Reading | | | Low Combustion Reading | | | Safety device(s) correct operation | Ventilation Provision satisfactory | Visual condition of flue and termination satisfactory | Flue Performance test | Appliance Serviced | Appliance safe to use |
| | | | | | | | | | | Ratio | CO ppm | CO2 % | Ratio | CO ppm | CO2 % | | | | | | |
| 1 | Kitchen Left Hob | Hob | Lamona | LAM1004 | FL | Yes | Yes | 20 | 2 | NA | NA | NA | NA | NA | NA | Yes | Yes | NA | NA | No | Yes |
| 2 | Kitchen Middle Hob | Hob | Lamona | LAM1004 | FL | Yes | Yes | 20 | 2 | NA | NA | NA | NA | NA | NA | Yes | Yes | NA | NA | No | Yes |
| 3 | Kitchen Right Hob | Hob | Lamona | LAM1004 | NA | Yes | Yes | 20 | 2 | NA | NA | NA | NA | NA | NA | Yes | NA | NA | NA | No | Yes |
| 4 | Bathroom Cupboard | Boiler | Baxi | Duo-tec 2 Combi 33 GA | BF | Yes | Yes | 20 | 30 | 0.0005 | 46 | 8.0 | NA | NA | NA | Yes | Yes | Yes | Pass | Yes | Yes |
| 5 | | | | | | | | | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | | | | | | | | | |

| Defects / Identified | | | | Labels and Warning Notice Issued | | | | CO Alarm(s) | | | | Smoke Alarm(s) | | | | | | | | | |
|----------------------|--|--|--|----------------------------------|--|--|----|-------------|--|--|--|----------------|--|--|--|--|--|--|--|--|--|
| 1 | | | | | | | No | | | | | | | | | | | | | | |
| 2 | | | | | | | No | | | | | | | | | | | | | | |
| 3 | | | | | | | No | | | | | | | | | | | | | | |
| 4 | | | | | | | No | | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | | | | | | | | | |

| | | |
|--------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|-------------------------------------|
| Emergency Control Accessible <input checked="" type="checkbox"/> Yes | Gas Tightness Satisfactory <input checked="" type="checkbox"/> Yes | Comments |
| Gas Installation Pipework Visual Inspection Satisfactory <input checked="" type="checkbox"/> Yes | | |
| Number of Appliances Tested <input type="text" value="4"/> | Equipotential Bonding <input checked="" type="checkbox"/> Yes | |
| NEXT INSPECTION DUE ON OR BEFORE <input type="text" value="30-Aug-2020"/> | | |

| Signatures | | Date | |
|-------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------|------|------------------------------------------|
| Issued by: Signed  | Received Signed by:  | Date | <input type="text" value="29-Jul-2019"/> |
| Print Name <input type="text" value="Mark Kneath"/> | Print Name <input type="text"/> | | |