

## **Landlord Gas Safety Record**

Cert. No. 2666

**BF Heating Services** 

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer						Job Address							Customer / Landlord							
Engineer	Ben Farley	Ben Farley				Name Address 279							Name Prasun Bhaumik							
Company	BF Heating	BF Heating Services				279					Company	any	Clifford Sinclair Limited							
Address	11 Cranbury Road					Lo	London Road						SS	40						
						Re	Reading							Craven Street						
	Reading													London						
					Post Code	1101 3112								201.001.						
Post Code	ost Code RG30 2XE					Tel. No						Post C	Code WC2N 5NG							
Tel No.												Tel. No	0	0845 0568402						
Gas Safe Reg 527170																				
ID Card No. 4714502																				
	4714302																			
Appliance D	etails						Inspec	ction Details												
Location	on Appliance Type		Make	Mode	el Flue Ty		Landlord's Appliance	Appliance Inspected	cted Operating Pressure (mbar)	Heat Input (kW/h)	High Combusti Reading	on Low Combustion Reading		Safety device(s) correct	Ventilation Provision	Visual condition of flue and	Flue Performance	Appliance Serviced	Appliance safe to use	
							Appliance		(IIIbai)		Ratio CO		io CO CO	operation	satisfactory	termination satisfactory	test	Serviced	to use	
1211			D .	020.0	1.1	D.C.			17.0(04/0)	20.00/ 1)	ppm		ppm %				n .	.,		
1 Kitche	n C	entral Heating Boiler	Baxi	830 Cd	ombi	RS	Yes	Yes	17.8(IWP) Flue:20.9%	30.89(net)	0.0012 103	8.9 0.00	001 9 8.	5 Yes	Yes	Yes	Pass	Yes	Yes	
2		Donei							1140.201370											
3																				
4																				
5																				
6																				
	ontified								Labels a	nd Warning No	otice Issued		larm(s)			Smoko	Alarm(s	1		
Defects / Identified							243015 and Marining Motice Issued					CO A	liai III(S)			SITIORE	Alaim(S			
1										NA										
2												CO A	larm(s) fit	ted	Yes	Smoke /	Alarm(s) fitt	:ed	Yes	
3														CO Al- 2224(2) to ata d						
5												CO Alarm(s) tested and Satisfactory Pass		Smoke Alarm(s) tested Pass and Satisfactory			Pass			
6											una s	acisiacco	y		una sac	Sidetory				
_					Corre															
Emergency Co	ntrol Access	sible Yes Gas	Tightness Satisfactory NA	٨	Comr	nents														
Gas Installation	n Pipework '	Visual Inspection	Satisfactory Yes																	
			•																	
Equipotent	ial Bonding	Yes																		
NEXT INSPEC	TION DUE	ON OR	18-Mar-2022																	
BEFORE																				
Signatures																				
Issued by:				leceived Signed						Da	te	26-Mar-2021								
		JAN Y	•	k	oy:															
Print Name		Ben Farley		F	Print Name															