



 [britishgas.co.uk/help](http://britishgas.co.uk/help)

 **0800 294 9678\***  
Mon - Fri 8am - 6pm

 **British Gas, Swallowfield 1,  
Wolverhampton Road, West  
Midlands, B69 2BG**

**Your HomeCare® Number  
22328096 4262028**

## Your Landlord's Gas Safety Certificate is over the page

- 0 This is an important document.
- 0 You should take a few moments now to read it.
- 0 You may need to refer to this certificate in the future.
- 0 Please file it somewhere safe.

### Key to Appliance Type Abbreviations

AGA Aga	INS Installation Premise
BBC Back Boiler Circulator	LB Large Boiler
BBF Back Boiler Fire	LBX Extra Large Boiler
BCO CO Detector	MWH Multitpoint Water Heater
CGE Electric/Gas Cooker	OVN Gas Oven
CHB Central Heating Boiler	SLC Split Level Cooker
CIR Circulator	SA Smoke Alarm
CKR Gas Cooker	SWH Single Point Water Heater
DGF Decorative Gas Fire	WAC Warm Air Conditioner
FRE Gas Fire	WAL Wall Heater
FRB Back Boiler Fire	WAU Warm Air Unit
FRC Back Circulator Fire	WAW Warm Air Unit and Water Heater
GOB Gas Oven	WH Water Heater
GRL Grill	WS Sink Water Heater
HGE Electric/Gas Hob	
HOB Hob	

### Key to Engineer findings

NCS or NTCS	Not to current standards
AR	At Risk
ID	Immediately Dangerous
PRV	Pressure relief valve

## Additional Landlord information

If a "YES" has been entered in the column titled "Indicate YES if unable to test", then the Landlord/Agent must obtain additional evidence from any person undertaking subsequent work on the appliance, that the appliance is operating safely.



Gas Safe  
Registration  
Number  
158205

# Landlord's Gas Safety Record

Landlords Inspection Service  
Swallowfield One  
Wolverhampton Road  
Oldbury  
West Midlands B69 2BG



This inspection is for gas safety purposes only in accordance with the Gas Safety (I & U) Regulations. Flues were inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the Flue integrity, construction and lining has not been carried out.

**TENANT DETAILS**

The Tenant  
Glyn Ceris, Deiniol Road  
Bangor LL57 2UP

**LANDLORD/AGENTS DETAILS**

Mr Wilson  
105 Woodfield Road  
Shrewsbury SY3 8HU

APPLIANCE DETAILS						INSPECTION DETAILS									
	LOCATION	TYPE	MAKE	MODEL	FLUE TYPE	Operating Value (See Key below)	Safety Device Correct Operation	Ventilation Satisfactory	FLUE PERFORMANCE		Visual Condition of Flue and Termination Satisfactory	Appliance Safe	Requested To Test	Indicate* YES if unable to test	
									Flue Flow Test	Spillage Test					
1	DINING ROOM	CHB	IDEAL	CLASSIC	ROOM-SEALED	11m	Yes	Yes	N/A	N/A	Yes	Yes	Yes	---	
2															
3															
4															
5															
DETAILS OF ANY DEFECTS IDENTIFIED						REMEDIAL ACTION TAKEN					LABELLED AND WARNING NOTICE ISSUED YES/NO	GAS INSTALLATION TIGHTNESS TEST AND VISUAL INSPECTION OF GAS			
1	NA					NA					N/A	<div style="border: 1px solid black; padding: 5px; text-align: center;"> <b>NEXT SERVICE CHECK DUE WITHIN 12 MONTHS</b> </div>			
2															
3															
4															
5															
This safety record is signed by electronic signature by						Print name STUART MILLS 2997773				Date 22 October 2013		Job No. 1316041295			
Number of Appliances Tested ...1.....						Page .....2... of .....2..									

**IT IS A LEGAL REQUIREMENT THAT THIS RECORD BE KEPT FOR A MINIMUM PERIOD OF TWO YEARS**